

EZ JACK LOW VOLTAGE PENDANT INSTALLATION INSTRUCTION FOR MARTE (PD156)




MONORAIL




- 1 Monorail Adapter place "U" grooved part with male threads over monorail.
- 2 Raise bottom of monorail adapter with female threads mating with "U" part male threads.
- 3 Rotate clockwise till tight.
- 4 Be careful not to cross-thread when tightening.





- 1 Strip insulated Cable aprox. 1/4" with sharp knife, make sure to not cut cable metal stranding, install EZ Jack Cable Adapter by loosening thumb screws, removing them. Place adapter ends over the stripped cable area, tighten thumbscrews into their threaded holes.
- 2 Raise pendant to mate with male threads, rotate clockwise till tight. Be careful not to cross-thread when tightening.




MONOPOINT




- Mount monopoint canopy per enclosed instructions.
- 2 Raise pendant to mate with male threads, rotate clockwise till tight. Be careful not to cross-thread when tightening.

EZ JACK LOW VOLTAGE PENDANT INSTALLATION INSTRUCTION FOR MARTE (PD156)







Feed coaxial cable as shown through applicable glass.




2 Rotate to raise or lower glass leveling nut. Raise or lower and fine adjust nut level so top of socket holder (threaded part) is level with top of glass.




3 Push the lamp pins all the way into the socket holes.








- 8 While inserting the inner wire into the connector look through the set screw hole to make sure that the stripped portion of the inner wire contacts end of the connector.
- 9 Hold the coaxial cable in place; replace and tighten the M3 set screw with the 1.5MM Allen wrench. Lightly tug on the coaxial cable to make sure that the set screw connection is tight.



- 10 The strain relief slots should be rotated 90° away from the M4 set screw.
- Slide and push the strain relief completely into the connector.
 This will force the outer wrapped wire to be inserted into the connector.
- **12** Tighten the M4 set screw with the 2mm allen wrench so that the strain relief holds the outer wrapped wire in place.



1

Slide the conical connector over the fixture connector.

To install the fixture, refer to the instructions provided with the system.

SAVE THESE INSTRUCTIONS