




1 Unpack and disassemble.




4 Mount crossbar.




2 Set strain relief at desired point on cord.



5 Wire cables.



3 Screw strain relief into the canopy



6 Reassemble canopy to ceiling, turn the power on.

